


WIRING DIAGRAM



F00237

**PARTS LIST FOR LESTER-MATIC CHARGER
MODEL 09080 TYPE 36LC40-4T12
115 VAC / 60 HZ**

PART NO.	QTY.	DESCRIPTION
09191S	1	CASE ASSEMBLY
09079S	1	TRANSFORMER ASSEMBLY
09041S	1	HEATSINK ASSEMBLY, W/ DIODES
08849S	2	DIODE ASSEMBLY
02367S	1	AMMETER
02002S	1	TIMER, 12 HOUR
02003S	1	KNOB, TIMER
02390S	1	CAPACITOR, 6.0 MFD, 660 VAC
02008S	1	BUSHING, 8P-2, INSULATOR FOR DC CORD
02028S	1	BUSHING, 7W-2, INSULATOR FOR AC CORD
02506S	1	CORDSET, AC
08511S	1	CORDSET, DC, NO PLUG
18771S	1	CORDSET, DC, W/ MOLDED PLUG, GRAY
08067S	1	CORDSET, DC, W/ LESTER PLUG
08069S	1	CORDSET, DC, W/ 50 AMP ANDERSON PLUG
08329S	1	CORDSET, DC, W/ 175 AMP ANDERSON PLUG
08313S	1	PLUG ASSEMBLY, 50 AMP ANDERSON PLUG
02957S	1	PLUG ASSEMBLY, 175 AMP ANDERSON PLUG
08774S	1	FUSE ASSEMBLY
22032S	1	CORDSET, AC