


WIRING DIAGRAM



L2120S16

PARTS LIST FOR LESTRONIC II BATTERY CHARGER
ADVANCE NOS. 388120 & 388109
LESTER MODELS 15765 & 16060
TYPE 36LC36-8ET 120 VAC / 60 HZ

MODEL 15765 (388120)

ADVANCE NO.	LESTER NO.	QTY.	DESCRIPTION
	19939S	1	CASE ASSEMBLY
	12805S	1	TRANSFORMER ASSEMBLY
1012095	02390S	1	CAPACITOR
	08774S	1	FUSE ASSEMBLY
	08329S	1	DC CORDSET, SB175 PLUG, GRAY
206919	10047S	1	RELAY, 24 VDC, 15 A
373066	12296S	1	TIMER KIT
388558	12356S	1	CONTROL CABLE
373058	13072S	1	AC CORDSET
	16823S	1	AMMETER, 50 AMP
	16946S	2	HEATSINK, W/ WIRE (1)
373050	02028S	1	BUSHING, 7W-2
	02008S	1	BUSHING, 8P-2
	01332	1	OWNERS MANUAL

MODEL 16060 (388109)

ADVANCE NO.	LESTER NO.	QTY.	DESCRIPTION
	20316S	1	CASE ASSEMBLY
	16105S	1	TRANSFORMER ASSEMBLY
1012095	02390S	1	CAPACITOR
373054	08776S	1	FUSE ASSEMBLY
373053	12284S	1	DC CORDSET, SB175 PLUG, RED
206919	10047S	1	RELAY, 24 VDC, 15 A
373062	11830S	1	TIMER KIT
373055	12813S	1	CONTROL CABLE
	13072S	1	AC CORDSET
	16369S	1	AMMETER, 30 AMP
	16894S	2	HEATSINK, W/ WIRE (1)
373050	02028S	2	BUSHING, 7W-2
	01351	1	OWNERS MANUAL