


WIRING DIAGRAM



F00237

PARTS LIST FOR LESTER-MATIC CHARGER
MODEL 09611 TYPE 36LC25-3.5T12
115 VAC / 60 HZ

PART NO.	DESCRIPTION
09612S	CASE ASSEMBLY
07425S	TRANSFORMER ASSEMBLY
16354S	HEATSINK ASSEMBLY, W/ DIODES
02000S	AMMETER
02002S	TIMER, 12 HOUR
02003S	KNOB, TIMER
02390S	CAPACITOR, 6.0 MFD, 660 VAC
02028S	BUSHING, 7W-2, INSULATOR FOR CORDSETS
02506S	CORDSET, AC, 14/3, 72"
03574S	CORDSET, AC, 14/3, 108"
08512S	CORDSET, DC, NO PLUG
14973S	CORDSET, DC, W/ SILICONE PLUG
08020S	CORDSET, DC, W/ LESTER PLUG
08607S	CORDSET, DC, W/ 50 AMP ANDERSON PLUG
08224S	CORDSET, DC, W/ 175 AMP ANDERSON PLUG
10536S	CORDSET, DC, 130", 50 AMP ANDERSON PLUG
10553S	CORDSET, DC, 190", 50 AMP ANDERSON PLUG
10716S	CORDSET, DC, 226", 50 AMP ANDERSON PLUG
07567S	CORDSET, DC, NO PLUG, W/ RING TERMINALS
08313S	PLUG ASSEMBLY, DC, 50 AMP ANDERSON PLUG
02957S	PLUG ASSEMBLY, DC, 175 AMP ANDERSON PLUG
08045S	LESTER DC RECEPTACLE (FOR VEHICLE)
08776S	FUSE ASSEMBLY